# Weathertzanon Assistance Program

# Work Order (Bid Form)

### **WORK ORDER INFORMATION**

Work Order Name: WO/10010MC2363/1

Work Order Type: Weatherization

Audit Name: Audit 2363

#### **CLIENT INFORMATION**

Client Name: Address:

Client ID: 10010MC2363

Alt. Client ID: 10010MC2363

#### **AGENCY INFORMATION**

**Agency:** Mid-Cumberland Community Action Agency **Agency Phone:** (615) 742-1113

Address: (PO Box 310) 233 Legends Drive Fax: (615) 742-3911

Lebanon, TN 37088 Email Address:

Agency Contact: Thomas, Tom Work Phone:

**Cell Phone:** (615) 715-2787

Email Address:

Company Name & License Number:	
Contractor's Signature:	

## **COMMENT**

AUDIT BY TOM THOMAS ON 6-23-11.
Audit and onsite review by John Batey on 1-9-12
SITE BUILT HOME
1600SF, VINYL SIDING EXTERIOR WALLS
ALL WORK MUST COMPLY WITH TENNESSEE WEATHERIZATION FIELD GUIDE, TWFG, AND LOCAL CODES.

Page 1 of 6

# Measures

I	Measure 1		L AND MASTIC DUCT ER BEDROOM	г воот т	0	Componen	ts			Inspected
C	ten		was loose and mostly repaired this boot but	-		•			nt	
						Estimated	1		Actual	
#	Material / Lab	oor L	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	1	NAILS AND MASTIC	Each	1					
O	ther Detail									
				1	Measur	e Sub Total:			Sub Total:	
	Field Notes:									

Λ	<i>l</i> leasure		vice and clean package ton	heat pum	ıp,	Componen	ts			Inspected
Ci	omment	poorly. During outside and ins airflow. and ex service Also ir addition	heatpump is of recent matural Unit is a Goodman 2.5 partially frozen, heat is had partially frozen, heat is defilter was very dirty to Client was complaining a terior fans, and compress is recommended.  Included in this service is to hal 6 new filters for client.  Evels are to be carefully oport to be turned in with in	ackage he e temp wa t pump wa the point c about rece or of unit s o replace 2	at pum s 57 d s oper of rest nt high seeme	np. legrees), hearing in aux ricting or aln n electric bills d to be func O" air return	at pump of heat striphost stop s. Both in tioning be filter and	coils o mode ping terior ut full		
		100.110		.,,,,,,		Estimated	•		Actual	
#	Material /	'Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecif	fied	Misc Material	Each	1					
0	ther Detai	il								
					Measur	e Sub Total:			Sub Total:	
	Field Note	es:								

	Measure 3 Ligh									
C	Comment									
					Estimated	d		Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Lighting	Compact FI 26 Watt	Each Lamp	1						
2	Labor	Compact FI 26 Watt	Each Lamp	1						
3	Lighting	Compact Fl 13 Watt	Each Lamp	4						
4	Labor	Compact Fl 13 Watt	Each Lamp	4						
5	Lighting	Compact FI 13 Watt	Each Lamp	3						
6	Labor	Compact Fl 13 Watt	Each Lamp	3						
7	Lighting	Compact Fl 13 Watt	Each Lamp	2						
8	Labor	Compact FI 13 Watt	Each Lamp	2						
C	Other Detail						_			
				Measur	e Sub Total:			Sub Total:		
	Field Notes:									

Measure 4 DWI	H Pipe Insulation			Componen	ts		1	Inspected
	neater is located in crawl due to height restrictions.	•	a and	is a "short" o	or "lowbo	y"		
_	-			Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Total	
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Comment Water h	H Tank Insulation neater is located in crawl due to height restrictions.	•	a and	Componen is a "short" o		y"	Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Hot Water Equip	DHW Tank Insulation	Each	<i>Qiy</i> 1	Omi Cost	lOlai	Qty	Omit Cost	TOTAL
2 Labor	DHW Tank Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	

Measure 6 Floor Ins. R-19				Componen	<i>t</i> s F1	Inspected			
Comment To inclu	de caulk sealing exterior	floor ban	d, 172	_			Andreal		
				Estimated		Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	1600						
<sup>2</sup> Labor	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	1600						
Miscellaneous Su	Caulk seal exterior floor band	Each	1						
4 Labor	Caulk seal exterior floor band -Labor	Each	1						
Other Detail									
			Measure	e Sub Total:		] ;	Sub Total:		
Field Notes:									
		Work O	rder Gra	nd Total:		Gran	d Total:		